

CERTIFICATE OF ACCREDITATION

This is to attest that

VORTEX FIRE SAFETY CONSULTANCY

SUITE 809, DUSSELDORF BUSINESS POINT, AL BARSHA 1 DUBAI, 392915, UNITED ARAB EMIRATES

Inspection Agency AA-849 (Type A)

has met the requirements of AC98, *IAS Accreditation Criteria for Inspection Agencies*, and has demonstrated compliance with ISO/IEC Standard 17020:2012, *Conformity assessment - Requirements for the operation of various types of bodies performing inspection*. This organization is accredited to provide the services specified in the scope of accreditation.

Effective Date March 25, 2024



President

SCOPE OF ACCREDITATION

International Accreditation Service, Inc.

3060 Saturn Street, Suite 100, Brea, California 92821, U.S.A. | www.iasonline.org

VORTEX FIRE SAFETY CONSULTANCY

www.vortexfec.com

Contact Name Mr. Faimeen Shah

Contact Phone +971 4 554 2475

Accredited to ISO/IEC 17020:2012

Effective Date March 25, 2024

Field and Range of Inspection	Regulations, Inspection Methods, Standards and/or Specifications
Management System Documentation: Vortex Fire Safety Consultancy QMS01-R12; Operational Manual, 18-010-01-09, Rev 9 (26 Feb 2024); Passive Inspection Manual, 18-011-01-04, Rev 4 (21 Feb 2024) supported by several procedures (details below) in line with the requirement of UAE Fire & Life Safety Code of Practice (2018 Edition), Abu Dhabi International Building Code (ADIBC) (2013 Edition) and 2018 Saudi Building Code (SBC).	
Through and Membrane- Penetration Firestop Systems	2021 International Building Code Sections 1705.18 and 1705.18.1; NFPA 5000:2024, Sections 40.9 and 40.9.1; ASTM E2174; UAE Fire & Life Safety Code of Practice (2018 Edition); Abu Dhabi International Building Code (ADIBC) (2013 Edition); 2018 Saudi Building Code (SBC) Section 1705.17.1 and Inspection Procedure 18-011A-01-04.
Fire Resistive Joint System and Building Perimeter Fire Barriers	2021 International Building Code Sections 1705.18 and 1705.18.2; NFPA 5000:2024, Sections 40.9 and 40.9.2; ASTM E2393; UAE Fire & Life Safety Code of Practice (2018 Edition); Abu Dhabi International Building Code (ADIBC) (2013 Edition); 2018 Saudi Building Code (SBC) Section 1705.17.2 and Inspection Procedure 18-011B-01-04.
Façade and Roofing Systems	2021 International Building Code Section 1705.17; NFPA 5000:2024, Section 40.4.2; UAE Fire & Life Safety Code of Practice (2018 Edition); Abu Dhabi International Building Code (ADIBC) (2013 Edition); 2018 Saudi Building Code (SBC) Section 1705.16 and Inspection Procedure, 18-011C-01-05.
Fire Door Assembly	NFPA 80:2022- Standard for Fire Doors and Other Opening Protectives, Chapter 5; UAE Fire & Life Safety Code of Practice (2018 Edition); Abu Dhabi International Building Code (ADIBC) (2013 Edition); 2018 Saudi Building Code (SBC) and Inspection Procedure 18-011D-01-04.



SCOPE OF ACCREDITATION

International Accreditation Service, Inc.

3060 Saturn Street, Suite 100, Brea, California 92821, U.S.A. | www.iasonline.org

Field and Range of Inspection	Regulations, Inspection Methods, Standards and/or Specifications
Sprayed Fire-Resistive Material (SFRM)	2021 International Building Code Section 1705.15; NFPA 5000:2024, Section 40.5; ASTM E 605 and ASTM E 736; AWCI Technical Manual 12-A; UAE Fire & Life Safety Code of Practice (2018 Edition); Abu Dhabi International Building Code (ADIBC) (2013 Edition); 2018 Saudi Building Code (SBC) Section 1705.14 and Inspection Procedure 18-011E-01-04.
Mastic and Intumescent Fire-Resistant Coating	2021 International Building Code Section 1705.16; ASTM D 7091 and ASTM E 736; AWCI Technical Manual 12-B; UAE Fire & Life Safety Code of Practice (2018 Edition); Abu Dhabi International Building Code (ADIBC) (2013 Edition); 2018 Saudi Building Code (SBC) Section 1705.15 and Inspection Procedure 18- 011F-01-04.
Fire Sprinkler & Standpipe Systems	2021 International Building Code Sections 3311, 3312; NFPA 5000:2024, Sections 55.3 & 55.4; UAE Fire & Life Safety Code of Practice (2018 Edition); Abu Dhabi International Building Code (ADIBC) (2013 Edition); 2018 Saudi Building Code (SBC) and Inspection Procedure 18-012A-01-02.

Other Office:

Abu Dhabi, UAE-Vortex Fire Safety Consultancy, Level 1 Cloud Spaces, Town Square, Yas Mall, Yas Island, Abu Dhabi, UAE

